

POCKET Blow Torch PART NO. 211689 B

TO IGNITE:

Push slowly down on the ignition button

TO EXTINGUISH:

Release the ignition button and the flame will extinguish

FILLING/REFILLING GAS:

Make sure torch is extinguished before filling and has cooled down. Hold the fuel cartridge in an upside down position. Insert the butane canister refill nozzle into the refilling valve and push down. Stop refilling once the gas starts to overflow. DO NOT OVERFILL. Do not try and ignite the torch immediately after filling, let the gas settle.

For use with TradeFlame Butane Gas Refill 60 g - Part No. 2312 or 200g - Part No. 2323

WARNING

To avoid injury or damage only ignite the torch when clear of face, hand, clothing or combustible materials. The burner/tip becomes extremely hot during and after operation, care must be taken to avoid accidental burns. Ensure flame is completely out after use.

Do not expose to temperature above 50°C / 120F.

Contains flammable gas under pressure, do not disassemble, puncture, drop or incinerate after use.

Do not attempt to repair or service this item. It is not user serviceable.

Do not use continuously for more than 5 minutes at a time.

Keep out of reach of children

